

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2018

Submitted Date:

03/27/2018

Document Number:

689500657**FIELD INSPECTION FORM**

Loc ID 315556 Inspector Name: GRANAHAN, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231031	WELL	TA	04/27/2017	OW	103-08700	UNION PACIFIC 122 X 21	TA

**General Comment:**

On location in regards to form 42 doc# 401573090 to witness MIT

Top of packer at 6295'

Top of perf at 6411'

116' between packer and top of perf - variance on file for greater than 100'

No casing or tubing pressure before or after test

Casing start psi 360

Casing 5 min psi 360

Casing 10 min psi 360

Casing final psi 360

0 psi change during test

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 231031 Type: WELL API Number: 103-08700 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: On location in regards to form 42 doc# 401573090 to witness MIT  
Top of packer at 6295'  
Top of perf at 6411'  
116' between packer and top of perf - variance on file for greater than 100'  
No casing or tubing pressure before or after test  
Casing start psi 360  
Casing 5 min psi 360  
Casing 10 min psi 360  
Casing final psi 360  
0 psi change during test

Corrective Action: Date: **Workover**

Comment: On location in regards to form 42 doc# 401573090 to witness MIT  
Top of packer at 6295'  
Top of perf at 6411'  
116' between packer and top of perf - variance on file for greater than 100'  
No casing or tubing pressure before or after test  
Casing start psi 360  
Casing 5 min psi 360  
Casing 10 min psi 360  
Casing final psi 360  
0 psi change during test

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					

Comment: No sediment flow evident

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT