


## Inspection Photos

Location Name: KAMMERZELL-65N66W 29SWNW

Location #: 329855



Kammerzell 29-5 well facing N.




Tank Battery facing SE. Berms appear inadequate for containment.



Inspection Photos

Location Name: KAMMERZELL-65N66W 29SWNW

Location #: 329855



Separator facing S.

**Corrective Action: unused equipment & trash.**

**Wet stains on dump lines.**

