

Inspection Photos  
Location Name: Kerr McGee – Troudt 44-7  
Spill/Release Pt. 453142



Well Sign



Excavation

**Inspection Photos**  
**Location Name: Kerr McGee – Troudt 44-7**  
**Spill/Release Pt. 453142**



**Ground water entering open excavation**



**Open excavation**