

Inspection Photos
Location Name: KP Kaufman – Facility 8 Consolidated Line
Spill/Release Pt. 452596



Excavator



Excavated area

Inspection Photos

Location Name: KP Kaufman – Facility 8 Consolidated Line
Spill/Release Pt. 452596



Excavation



Condensate floating on water in the excavation



Inspection Photos

Location Name: KP Kaufman – Facility 8 Consolidated Line
Spill/Release Pt. 452596



Field Screening walls of the excavation



Field screening walls of the excavation

