

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401589446

Receive Date:  
\_\_\_\_\_

Report taken by:  
\_\_\_\_\_

**Site Investigation and Remediation Workplan (Initial Form)**

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

**OPERATOR INFORMATION**

Name of Operator: <u>WEXPRO COMPANY</u>	Operator No: <u>95960</u>	<b>Phone Numbers</b> Phone: <u>(307) 352-7514</u> Mobile: <u>(307) 371-5695</u>
Address: <u>P O BOX 45003</u>		
City: <u>SALT LAKE CITY</u> State: <u>UT</u> Zip: <u>84145-0601</u>		
Contact Person: <u>Tammy Fredrickson</u> Email: <u>Tammy.Fredrickson@dominionenergy.com</u>		

**PROJECT, PURPOSE & SITE INFORMATION**

**PROJECT INFORMATION**  
Remediation Project #: \_\_\_\_\_ Initial Form 27 Document #: 401589446

**PURPOSE INFORMATION**

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

**SITE INFORMATION**      N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>312993</u>	API #: _____	County Name: <u>MOFFAT</u>
Facility Name: <u>WILSON, F-612N100W 23SWNW</u>		Latitude: <u>40.985716</u>	Longitude: <u>-108.609767</u>
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: <u>SWNW</u>	Sec: <u>23</u>	Twp: <u>12N</u>	Range: <u>100W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>

**SITE CONDITIONS**

General soil type - USCS Classifications SC      Most Sensitive Adjacent Land Use Non-crop land/Rangeland

Is domestic water well within 1/4 mile? Yes      Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

**Other Potential Receptors within 1/4 mile**

There are no other potential receptors within 1/4 mile.

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input type="checkbox"/> Oil                       | <input type="checkbox"/> Tank Bottoms                |  |
| <input checked="" type="checkbox"/> Condensate     | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Minimal/Moderate	Soil was visually inspected. This spill is on an active well pad.

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Operator isolated and depressured all related equipment and reported the spill. A one-call was initiated to get all lines marked for excavation. A liner was brought to location to hold contaminated soil that was excavated.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

In order to verify that all contaminated soil has been removed; four soil samples will be obtained and tested for GRO/DRO prior to obtaining a Table 910-1 analysis. Location of samples are shown on the attached photos. One at the bottom of the trench under the old pipe where leak occurred, one on each side wall under the coal seam, and one at the far end of the trench.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 0

Number of soil samples exceeding 910-1         

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 900

### NA / ND

NA Highest concentration of TPH (mg/kg)         

NA Highest concentration of SAR         

BTEX > 910-1         

Vertical Extent > 910-1 (in feet) 6

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)         

Number of groundwater monitoring wells installed         

Number of groundwater samples exceeding 910-1         

NA Highest concentration of Benzene (µg/l)         

NA Highest concentration of Toluene (µg/l)         

NA Highest concentration of Ethylbenzene (µg/l)         

NA Highest concentration of Xylene (µg/l)         

NA Highest concentration of Methane (mg/l)         

### Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 0

Volume of liquid waste (barrels) 2

Is further site investigation required?

Wexpro will obtain soil samples to be analyzed confirming all contaminated soil was removed.

# REMEDIAL ACTION PLAN

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Contaminated soil was removed and placed on a liner. Contaminated soil will be hauled by truck to the R-360 Disposal site in LaBarge, WY on Monday, April 2, 2018.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Wexpro will complete initial soil analysis to determine if contamination has been completely removed. If analysis determines no additional contamination a soil analysis will be conducted testing for Table 910-1 requirements. Upon passing of final analysis results the open trench will be backfilled.

## Soil Remediation Summary

In Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Air sparge / Soil vapor extraction  
\_\_\_\_\_ Natural Attenuation  
Yes \_\_\_\_\_ Other \_\_\_\_\_  
\_\_\_\_\_ Temporarily placed on a liner.

Ex Situ

Yes \_\_\_\_\_ Excavate and offsite disposal  
\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 0  
\_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_  
\_\_\_\_\_ Excavate and onsite remediation  
\_\_\_\_\_ Land Treatment  
\_\_\_\_\_ Bioremediation (or enhanced bioremediation)  
\_\_\_\_\_ Chemical oxidation  
\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

No \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
No \_\_\_\_\_ Chemical oxidation  
No \_\_\_\_\_ Air sparge / Soil vapor extraction  
No \_\_\_\_\_ Natural Attenuation  
No \_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

There was no impact to groundwater.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

Frequency:  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_  
Report Type:  Groundwater Monitoring  Land Treatment Progress Report  O&M Report  
 Other Final Analysis data. \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Produced water and condensate contaminated soil. Soil was removed and will be hauled to R-360 disposal facility.

Volume of E&P Waste (solid) in cubic yards 0

E&P waste (solid) description Contaminated Soil

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: R-360

Volume of E&P Waste (liquid) in barrels 2

E&P waste (liquid) description Produced water and condensate

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: R-360

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

This spill occurred on an existing active well pad. There will be no reclamation at this time.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 03/19/2018

Actual Spill or Release date, if known. 03/19/2018

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/20/2018

Date of commencement of Site Investigation. 03/19/2018

Date of completion of Site Investigation. 03/20/2018

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 03/19/2018

Date of completion of Remediation. 03/21/2018

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

**OPERATOR COMMENT**

On March 26, 2018 the damaged pipe was cut off and removed from service. The remaining pipe for both the water dump line and oil dump line were pressure tested with gas from the wellhead to 180 psi and both held and confirmed there was no further damage or spill potential. New pipe will be attached to the existing pipe and put back into service. Once soil analysis confirms no further contamination new soil will be hauled in to backfill the excavated area. Cubic yards of contaminated soil will be reported once determined by trucking and disposal.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Tammy Fredrickson

Title: Senior Permit Agent

Submit Date: \_\_\_\_\_

Email: Tammy.Fredrickson@dominionenergy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: \_\_\_\_\_

**COA Type****Description**

--	--

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

401590075	MAP
401590076	OTHER
401590079	OTHER
401591643	SITE INVESTIGATION PLAN

Total Attach: 4 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)