

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 1: Location, looking SW



Photo 2: Wellheads, looking S

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 3: Weeds, debris N of battery



Photo 4: Weeds, unused equipment at NW corner of location

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 5: Stained soil at Dacono 3 wellhead



Photo 6: Debris, weeds on NE side of location

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 7: Unused barrels, weeds, in between Dacono 3 and 1.



Photo 8: Stained soil, contaminant migration at Dacono 1

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 9: Unused ECD, weeds on E side of location (SE of Dacono 1)



Photo 10: Unused rods on E side of location. Weeds.

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 11: Unused horizontal separators on SE corner of location



Photo 12: Unused separators, rods in center of location (E of compressor)

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



**Photo 13: Unused equipment, debris on W side of location
(S of tank battery)**



**Photo 14: Stained soil, unused equipment, debris in
compressor house**

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 15: Debris in compressor house



Photo 16: Unused equipment around compressor house

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 17: Signs for prior operator on SE side of compressor house.



Photo 18: Unused equipment, weeds on SW side of location house.

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 19: Decals on sign are for prior operator, emergency contact numbers for prior operator.



Photo 20: Stained soil at crude oil loadout.

Inspection Photos
Location Name: Dacono 3
Location ID: 336404



Photo 21: Dacono 4 is PA, does not produce to this battery.

