

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2018

Submitted Date:

03/30/2018

Document Number:

680303125

FIELD INSPECTION FORM

Loc ID 454199 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10657
Name of Operator: PCR OPERATING LLC
Address: 4040 BROADWAY STREET #510
City: SAN ANTONIO State: TX Zip: 78209

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Wehrer, Gene	(970) 380-4860	gwehrer@passcreekresource.com	Adena Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454198	WELL	XX	03/05/2018		087-08225	JESS 158-13-34	DG

General Comment:

[Drilling Inspection FIR: Day \(3\)](#)

Location

Lease Road:

	Type Access		
comment:	Two track off Ct. Rd.		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type DRILLING/RECOMP		
Comment:	Sign at entrance to drill site @ Ct.Rd.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory		
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 454198 Type: WELL API Number: 087-08225 Status: XX Insp. Status: DG

Well Drilling

Rig: Rig Name: Nebco #12 Pusher/Rig Manager: Gary Naill
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: 800 Safety Plan: YES

Drill Fluids

Management:

Lined Pit: NO Unlined Pit: YES Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: NO Disposal Location: solids stored on site during drilling

Comment: Day (1) March 24, Spud. Drilled 12.25" surface hole to 422' (10) jts. 8 5/8" casing set @ 408'. Cemented w/290 sks. Displaced (2) bbls. to pit.
 Day (2) March 25, Drilling Pierre Shale - TD = 3364' Surveying drift- 1013'=0, 1514'-1/4 deg., 2018'=0, 2520'-1/2 deg. 3021' -1/2 deg., Mud weight 8.50, Vis. -29
 Day (3) March 26, Drilling TD=5117' Surveys: 3520' - 1 deg., 4012' - 1/2 deg., 4527' -3/4 deg., 5022' -1/4 deg., mud 9.2, Vis. -51, wtr loss -8, cake 2/32.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Day (3) drilling. FIR Day(1)+Day (2)+Day (3) reported in this FIR.	schureky	03/30/2018