

O10A 596 Pad
N. Parachute WF04B
Api# 05-045-12353
Inspection # 689701225



Location sign photo

O10A 596 Pad
N. Parachute WF04B
Api# 05-045-12353
Inspection # 689701225



Drilling chemicals and equipment has been removed from location.

O10A 596 Pad
N. Parachute WF04B
Api# 05-045-12353
Inspection # 689701225



Spilled materials and debris have been cleaned from location surface.