

# *Inspection Photos*

*Loc# 335939*

*Operator: Caerus*

*Inspection Number: 680102812*

*Inspection Date: 3/28/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of main Location area to Northwest.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335939



Photo#2:  
Area added on to Location at South end.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335939



Photo#3:

Area added on to Location at North end..

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335939




Photo#4:  
View over thirty-two Conductors set.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335939



Photo#5:

Close up views of spaces between concrete & conductor & rat hole casings which could entrap wildlife.

March 28, 2018

Photo#6:



Photo#7:  
Aerial view of Location 6/3/2014

March 28, 2018



Photo#8:  
Equipment at South end of main Location area.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335939