

Inspection Photos
Location Name: Caerus Location 335875
3/28/2018



DUCs looking North



Location showing ASTs and separators