

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2018

Submitted Date:

03/30/2018

Document Number:

680303126

**FIELD INSPECTION FORM**

Loc ID 454199 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10657  
Name of Operator: PCR OPERATING LLC  
Address: 4040 BROADWAY STREET #510  
City: SAN ANTONIO State: TX Zip: 78209

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Wehrer, Gene	(970) 380-4860	gwehrer@passcreekresource.com	<a href="#">Adena Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454198	WELL	XX	03/05/2018		087-08225	JESS 158-13-34	DG

**General Comment:**

[Drilling Day \(4\)](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off Ct. Rd.		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	Sign located at entrance of location off Ct.Rd.		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 454198 Type: WELL API Number: 087-08225 Status: XX Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Nebco #12 Pusher/Rig Manager: Gary Naill  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 800 Safety Plan: YES

**Drill Fluids**

**Management:**

Lined Pit: NO Unlined Pit: YES Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: Solids held on site during drilling

Comment: Day (4) Drilling Formation - Niobrara TD = 5669'.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Drilling Day (4)</a>	schureky	03/30/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401593175	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4420971">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4420971</a>