

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2018

Submitted Date:

03/28/2018

Document Number:

691300073

FIELD INSPECTION FORM

Loc ID 332839 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296130	WELL	PR	03/03/2011	GW	123-25897	BALLFIELD Y6 7-7-31	PR
296131	WELL	PR	03/03/2011	GW	123-25896	FARMERS Y7 6-6-31	PR
296270	WELL	PR	09/02/2009	GW	123-26712	COMMONS Z2 2-2-6	PR
418146	WELL	PR	12/17/2010	GW	123-31835	MAIN Y3 6-8-31	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Shared rod iron around wellheads

Corrective Action:

Date: _____

Equipment:

Type: Plunger Lift

4

corrective date

Comment: All wells on location run plunger lift.

Corrective Action:

Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 296130 Type: WELL API Number: 123-25897 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
	Well flows to battery#435366	
Corrective Action:		Date:

Facility ID: 296131 Type: WELL API Number: 123-25896 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
	Well flows to battery#435366	
Corrective Action:		Date:

Facility ID: 296270 Type: WELL API Number: 123-26712 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
	Well flows to battery#435366	
Corrective Action:		Date:

Facility ID: 418146 Type: WELL API Number: 123-31835 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
	Well flows to battery#435366	
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
All wells flow to battery#435366	kraicha	03/28/2018
All tanks and surface equipment are identified on the LaSalle Directional Project 2 (332840) inspection form. See document#69130069 for details.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401589432	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4416480
691300074	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4416448