

Interim Reclamation Inspection

March 30, 2018

Operator: EWS 1 DJ BASIN LLC - #10640

API: 05-123-39891

Inspection Document #: 682403442

Weld County, CO

NENW Section 26 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EWS #1A
API: 05-123-39891



Photo 1. Photo taken from the northwest perimeter of the location, facing East. Waste on location from recent drilling operations needs to be removed per Rule 603.f.



Photo 2. Photo taken from the northeast perimeter of the location, facing South. Appears to be a ditch installed along the eastern perimeter of the location. This was the only observed stormwater BMP, other than gravel at the location.

Inspection Photos
Location Name: EWS #1A
API: 05-123-39891



Photo 3. Photo taken from the southeast perimeter of the location, facing West. There was no observed perimeter stormwater BMP along the southern location.



Photo 4. Photo taken from the southwest perimeter of the location, facing South. See comments under Photo 3.