

Interim Reclamation Inspection

March 30, 2018

Operator: EWS 1 DJ BASIN LLC - #10640

API: 05-123-39770

Inspection Document #: 682403444

Weld County, CO

NWNW Section 26 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EWS #1
API: 05-123-39770



Photo 1. Photo taken from the approximate center of the location, facing East. Operator has failed to perform interim reclamation on areas not needed for production operations per Rule 1003.b.



Photo 2. Photo taken from the approximate center of the location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: EWS #1
API: 05-123-39770



Photo 3. Photo taken from the approximate center of the location, facing West. See comments under Photo 1.



Photo 4. Photo taken from the approximate center of the location, facing South. See comments under Photo 1.