

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2018

Submitted Date:

04/03/2018

Document Number:

689701237**FIELD INSPECTION FORM**

| Loc ID 334682 | Inspector Name: LONGWORTH, MIKE | On-Site Inspection <input type="checkbox"/> | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|------------------------------------|---|---|--------------|-----------|-------------------------------|-------------|-------------------|---------------|---------------------------------------|---------------------------|------|----|------------|----|-----------|----------------------|----|--------|------|----|------------|----|-----------|---------------------|----|--------|------|----|------------|----|-----------|----------------------|----|--------|------|----|------------|----|-----------|------------------------|----|--------|------|----|------------|----|-----------|-----------------------------|----|--------|------|----|------------|----|-----------|-------------------------------|----|--------|------|----|------------|----|-----------|-----------------------------|----|--------|------|----|------------|----|-----------|------------------------|----|
| 2A Doc Num: _____ | | | Findings: 11 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Contact Information: <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, Caerus Piceance</td> <td></td> <td>COGCC.inspections@caerusoilandgas.com</td> <td>Piceance inspections only</td> </tr> </table> | | | | Contact Name | Phone | Email | Comment | , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Contact Name | Phone | Email | | Comment | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Inspected Facilities: <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>286066</td><td>WELL</td><td>PR</td><td>01/17/2007</td><td>GW</td><td>045-12603</td><td>FEDERAL 20-10 (PN20)</td><td>PR</td></tr> <tr><td>286631</td><td>WELL</td><td>PR</td><td>01/07/2007</td><td>GW</td><td>045-12713</td><td>FEDERAL 20-12(PN20)</td><td>PR</td></tr> <tr><td>413026</td><td>WELL</td><td>PR</td><td>07/12/2011</td><td>GW</td><td>045-18708</td><td>Federal 20-11 (PN20)</td><td>PR</td></tr> <tr><td>413029</td><td>WELL</td><td>PR</td><td>07/12/2011</td><td>GW</td><td>045-18711</td><td>Federal 20-14BB (PN20)</td><td>PR</td></tr> <tr><td>415750</td><td>WELL</td><td>PR</td><td>07/12/2011</td><td>GW</td><td>045-19158</td><td>Federal Gardner 20-7 (PN20)</td><td>PR</td></tr> <tr><td>415795</td><td>WELL</td><td>PR</td><td>07/12/2011</td><td>GW</td><td>045-19163</td><td>Federal Gardner 20-7BB (PN20)</td><td>PR</td></tr> <tr><td>415799</td><td>WELL</td><td>PR</td><td>07/12/2011</td><td>GW</td><td>045-19164</td><td>Federal Gardner 20-6 (PN20)</td><td>PR</td></tr> <tr><td>416168</td><td>WELL</td><td>AL</td><td>05/24/2012</td><td>LO</td><td>045-19226</td><td>Federal Gardner 20-6BB</td><td>AL</td></tr> </tbody> </table> | | | Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | 286066 | WELL | PR | 01/17/2007 | GW | 045-12603 | FEDERAL 20-10 (PN20) | PR | 286631 | WELL | PR | 01/07/2007 | GW | 045-12713 | FEDERAL 20-12(PN20) | PR | 413026 | WELL | PR | 07/12/2011 | GW | 045-18708 | Federal 20-11 (PN20) | PR | 413029 | WELL | PR | 07/12/2011 | GW | 045-18711 | Federal 20-14BB (PN20) | PR | 415750 | WELL | PR | 07/12/2011 | GW | 045-19158 | Federal Gardner 20-7 (PN20) | PR | 415795 | WELL | PR | 07/12/2011 | GW | 045-19163 | Federal Gardner 20-7BB (PN20) | PR | 415799 | WELL | PR | 07/12/2011 | GW | 045-19164 | Federal Gardner 20-6 (PN20) | PR | 416168 | WELL | AL | 05/24/2012 | LO | 045-19226 | Federal Gardner 20-6BB | AL |
| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 286066 | WELL | PR | 01/17/2007 | GW | 045-12603 | FEDERAL 20-10 (PN20) | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 286631 | WELL | PR | 01/07/2007 | GW | 045-12713 | FEDERAL 20-12(PN20) | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 413026 | WELL | PR | 07/12/2011 | GW | 045-18708 | Federal 20-11 (PN20) | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 413029 | WELL | PR | 07/12/2011 | GW | 045-18711 | Federal 20-14BB (PN20) | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 415750 | WELL | PR | 07/12/2011 | GW | 045-19158 | Federal Gardner 20-7 (PN20) | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 415795 | WELL | PR | 07/12/2011 | GW | 045-19163 | Federal Gardner 20-7BB (PN20) | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 415799 | WELL | PR | 07/12/2011 | GW | 045-19164 | Federal Gardner 20-6 (PN20) | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 416168 | WELL | AL | 05/24/2012 | LO | 045-19226 | Federal Gardner 20-6BB | AL | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| General Comment: <div style="height: 100px;"></div> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Location

| | | | |
|--------------------|------|-------|--|
| Lease Road: | | | |
| Type | Main | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused signs on the ground at entrance. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 05/04/2018 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | LOCATION | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 3 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 5 | | |
| Comment: | | | |

| | | | |
|-----------------------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 7 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 500 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|----------|----|--|
| Yes/No | NO | |
| Comment: | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 286066 | Type: | WELL | API Number: | 045-12603 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 286631 | Type: | WELL | API Number: | 045-12713 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 413026 | Type: | WELL | API Number: | 045-18708 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 413029 | Type: | WELL | API Number: | 045-18711 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 415750 | Type: | WELL | API Number: | 045-19158 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 415795 | Type: | WELL | API Number: | 045-19163 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 415799 | Type: | WELL | API Number: | 045-19164 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 416168 | Type: | WELL | API Number: | 045-19226 | Status: | AL | Insp. Status: | AL |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |
| Ditches | Pass | | | | | |
| Berms | Pass | | | | | |
| | | Culverts | Pass | | | |
| | | Ditches | Pass | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 689701238 | Inspection 689701237 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4424321 |