

Inspection Photos
Location Name: Titanium 26-10-7HI & 2
API: 05-057-06094



Photo 1. Overview of location taken at entrance facing west.

Inspection Photos
Location Name: Titanium 26-10-7HI & 2
API: 05-057-06094



Photo 2. No capacity on crude oil tanks.



Photo 3. No capacity on produced water tank.