

Inspection Photos
Location Name: Coalmont 3-13H
API: 05-057-06508



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Coalmont 3-13H
API: 05-057-06508



Photo 2. Stained soil at wellhead.



Photo 3. Stained soil at wellhead.