

Inspection Photos

Location Name: Spill/Release Point ID #451553

REM #10395



Access to Spill/Release Point ID #451553.



Water bars and slope roughening controlling erosion along access.

Inspection Photos
Location Name: Spill/Release Point ID #451553
REM #10395



Spill/Release Point.

Project area has perimeter fencing.

Inspection Photos
Location Name: Spill/Release Point ID #451553
REM #10395



View along northern edge of project area.



Wattles on downhill side of project area have been destroyed/require attention.

Inspection Photos
Location Name: Spill/Release Point ID #451553
REM #10395



View of southern edge of project area.



Water and gas risers.