

Inspection Photos
Location Name: Klaenhammer 2
API: 05-081-06020



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Previous operator on tank label. Stained soil. Vegetation on and in berm.