

Inspection Photos  
Location Name: Klaenhammer 1  
API: 05-081-06013



**Photo 1. Overview of location taken at entrance facing south.**

Inspection Photos  
Location Name: Klaenhammer 1  
API: 05-081-06013



**Photo 2. Vegetation in berm adjacent to tank.**



**Photo 3. Pit.**