

Inspection Photos  
Location Name: McCallum Unit 18  
API: 05-057-05058



**Photo 1. Overview of location taken at entrance facing west.**



**Photo 2. No emergency contact on wellhead sign.**