

Inspection Photos
Location Name: Skurich/Rothe #6A
API: 05-123-20697



Photo 1: Wellhead, looking W



Photo 2:, location, looking W

Inspection Photos
Location Name: Skurich/Rothe #6A
Location: 331446



Photo from prior inspection for comparison



Photo 3: Stained soil removed at separator