

Inspection Photos
Location Name: Skurich Roth 42-6
Location: 251559



Photo 1: Location looking N



Photo 2: Wellhead location looking W

Inspection Photos
Location Name: Skurich Roth 42-6
Location: 251559



Photo from prior inspection for comparison



Photo 3: Meter run removed

Inspection Photos
Location Name: Skurich Roth 42-6
Location: 251559



Photo from prior inspection for comparison



Photo 4: Debris W of location

Inspection Photos
Location Name: Skurich Roth 42-6
Location: 251559



Photo 5: Unused fencing at N side of location