

Field Inspection Report Resolution

March 16, 2018

Operator: CAPTIVA ENERGY PARTNERS LLC- #10658

Location ID: 452112

Inspection Document #: 682403364

Weld County, CO

NENE Section 5 T3N R68W



Paul Onsager, Co-founder

P.O. Box 281108

Lakewood, CO 80228

720-635-7813

ponsager@captivaep.com

Inspection Photos from Captiva Energy Partners LLC
Location Name: Stillroven Farm Pad
Location ID: 452112
Inspection: 682403364



Photo 1. Photo taken from south of the drilled well looking north showing removal of E&P waste (3/16/18)



Photo 2. Photo showing stabilization of the sediment trap on the SW corner of the pad. (3/16/18)

Inspection Photos from Captiva Energy Partners LLC
Location Name: Stillroven Farm Pad
Location ID: 452112
Inspection: 682403364



Photo 3. Photo looking south showing compaction of berm on west side of location. (3/16/18)



Photo 4. Photo looking north showing compaction of berm on west side of location. (3/16/18)

Inspection Photos from Captiva Energy Partners LLC
Location Name: Stillroven Farm Pad
Location ID: 452112
Inspection: 682403364



Photo 5. Photo showing stabilization of sediment trap on NW corner of location. (3/16/18)



Photo 6. Photo looking SE showing vehicle tracking pad installed at entrance. (3/16/18)