

# *Inspection Photos*

*Loc# 311674*

*Operator: Caerus*

*Inspection Number: 680102826*

*Inspection Date: 3/28/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location area to East.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 311674





Photo#2:

View of Interim Reclamation on Cut slopes to North & East of pad.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 311674





Photo#3:  
East side of Access road ditch needs maintenance.

Photo#4:

March 28, 2018



Photo#5:

Plowing has moved material off road into edge of Reclamation area; creating disturbance

Photo#6:

March 28, 2018