

Inspection Photos
Location Name: Federal 11-90-26 #1
API: 05-051-06060



Federal 11-90-26 #1 pump jack and well head.



Prime mover has been removed from pumping unit.

Inspection Photos
Location Name: Federal 11-90-26 #1
API: 05-051-06060



Federal 11-90-26 #1 tank battery.



Peeling paint and rust present on second AST.