

Inspection Photos
Location Name: Log Cabin #1
API: 123-13426



Signage at battery

Inspection Photos
Location Name: Log Cabin #1
API: 123-13426



Wellhead & Pumping Unit. Corrective Action: Weeds growing up around wellhead and pumping unit. Chemical drum appears to be unused.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Log Cabin #1
API: 123-13426

**Wellhead detail. Corrective
Action: Stuffing box appears to
have been leaking, resulting in
staining of wellhead equipment
and surrounding soils.**



Apr 2, 2018 1:47:28 PM
40.48068783N 104.59943998W
Greeley



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Log Cabin #1
API: 123-13426



Location photo



Inspection Photos
Location Name: Log Cabin #1
API: 123-13426



Tank battery.



Inspection Photos
Location Name: Log Cabin #1
API: 123-13426

Produced water tank detail.
**Corrective action: Produced
water tank appears to have no
placarding.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources