

Inspection Photos
Location Name: Behring 23-10
Location ID: 305225



Photo from prior inspection for comparison



Photo 1: Pump jack removed. Electric box still present.



Inspection Photos
Location Name: Behring 23-10
Location ID: 305225



Photo 2: Unused spool



Photo 3: Deadman on location

