

Inspection Photos
Location Name: State 36-6
Location ID: 310587



Photo 1: Wellhead, looking S



Inspection Photos
Location Name: State 36-6
Location ID: 310587



Photo from prior inspection for comparison



Photo 2: Subsidence on drilling pit

Inspection Photos
Location Name: State 36-6
Location ID: 310587



Photo from prior inspection for comparison



Photo 3: Subsidence on drilling pit

Inspection Photos
Location Name: State 36-6
Location ID: 310587



Photo 4: Stained soil from pump jack



Photo 4: Stained soil removed.