

# *Inspection Photos*

*Loc# 335690*

*Operator: Caerus*

*Inspection Number: 680102834*

*Inspection Date: 3/28/2018*





Photo#1:  
Overview of Location area to Southwest.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335690



Photo#2:

What appears to be unused equipment is in main Well Pad area.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335690



Photo#3:  
What appears to be unused equipment is in main Well Pad area.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335690



Photo#4:  
What appears to be unused equipment is in main Well Pad area.

March 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335690