

# *Inspection Photos*

*Loc# 415182*

*Operator: Caerus*

*Inspection Number: 680102836*

*Inspection Date: 3/30/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overview of Location from entry to North East.

March 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 415182



Photo#2:  
Concrete debris is at East end of Location.

March 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 415182





Photo#3:

Aerial view of Location. Areas of Location no longer needed for Use have not been Reclaimed.

March 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 415182