

Inspection Photos

Loc# 335680

Operator: Caerus

Inspection Number: 680102838

Inspection Date: 3/29/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to North.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 335680



Photo#2:

2015 Aerial of Location; Pit has been closed since this Image. Dotted red line marks road with stormwater erosion; detailed in following photos.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 335680



Photo#3:
Erosion is occurring on road that leads off Southwest corner of pad.



Photo#4:

March 29, 2018



Photo#5:
Erosion is occurring on road that leads off Southwest corner of pad

March 29, 2018



Photo#6:



Photo#7:
Sediment is being deposited at pooling area at end of road in previous photos.

March 29, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 335680



Photo#8:

Maintenance is needed on main access road where it leads into Location.

March 29, 2018



Photo#9:



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 335680