

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

04/05/2018

Document Number:

680102834**FIELD INSPECTION FORM**

Loc ID 335690	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 4 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281800	WELL	PR	08/22/2007	GW	045-11539	N. PARACHUTE CP 11A-04 K04 596	RI
281804	WELL	SI	01/01/2017	GW	045-11543	NORTH PARACHUTE CP10D-4 K04 596	RI
281805	WELL	SI	06/01/2016	GW	045-11544	N. PARACHUTE CP11D 04 K04596	RI
281806	WELL	PR	08/22/2007	GW	045-11545	N PARACHUTE CP09B-04 K04 596	RI
429281	WELL	XX	05/06/2014	LO	045-21516	N Parachute UWF15A-05K04596	RI
429282	WELL	XX	05/05/2014	LO	045-21517	N Parachute UWF13C-04K04596	RI
429283	WELL	XX	05/05/2014	LO	045-21518	N Parachute UWF07D-05K04596	RI
429284	WELL	XX	06/13/2014	LO	045-21519	N Parachute UWF09B-05K04596	RI
429286	WELL	XX	05/05/2014	LO	045-21521	N Parachute UWF10D-05K04596	RI
429287	WELL	XX	05/05/2014	LO	045-21522	N Parachute UWF12A-04K04596	RI
429288	WELL	XX	05/06/2014	LO	045-21523	N Parachute UWF15B-05K04596	RI
429289	WELL	XX	05/05/2014	LO	045-21524	N Parachute UWF10E-05K04596	RI
429290	WELL	XX	05/05/2014	LO	045-21525	N Parachute UWF12E-04K04596	RI
429292	WELL	XX	05/05/2014	LO	045-21527	N Parachute UWF13A-04K04596	RI
429294	WELL	XX	04/30/2014	LO	045-21529	N Parachute UWF07C-05K04596	RI
429296	WELL	XX	05/05/2014	LO	045-21531	N Parachute UWF13E-04K04596	RI

429297	WELL	XX	05/05/2014	LO	045-21532	N Parachute UWF13B-04K04596	RI
429298	WELL	XX	05/06/2014	LO	045-21533	N Parachute UWF15C-05K04596	RI
429299	WELL	XX	05/05/2014	LO	045-21534	N Parachute UWF10C-05K04596	RI
429300	WELL	XX	05/05/2014	LO	045-21535	N Parachute UWF07E-05K04596	RI
429301	WELL	XX	05/05/2014	LO	045-21536	N Parachute UWF10A-05K04596	RI
429302	WELL	XX	04/30/2014	LO	045-21537	N Parachute UWF05E-04K04596	RI
429306	WELL	XX	05/15/2014	LO	045-21541	N Parachute UWF05D-04K04596	RI
429307	WELL	XX	05/05/2014	LO	045-21542	N Parachute UWF12C-04K04596	RI
429308	WELL	XX	04/30/2014	LO	045-21543	N Parachute UWF05C-04K04596	RI
429309	WELL	XX	05/05/2014	LO	045-21544	N Parachute UWF13D-04K04596	RI

General Comment:

This is a Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

Inspected Facilities				
Facility ID: <u>281800</u>	Type: <u>WELL</u>	API Number: <u>045-11539</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>281804</u>	Type: <u>WELL</u>	API Number: <u>045-11543</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>281805</u>	Type: <u>WELL</u>	API Number: <u>045-11544</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>281806</u>	Type: <u>WELL</u>	API Number: <u>045-11545</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429281</u>	Type: <u>WELL</u>	API Number: <u>045-21516</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429282</u>	Type: <u>WELL</u>	API Number: <u>045-21517</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429283</u>	Type: <u>WELL</u>	API Number: <u>045-21518</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429284</u>	Type: <u>WELL</u>	API Number: <u>045-21519</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429286</u>	Type: <u>WELL</u>	API Number: <u>045-21521</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429287</u>	Type: <u>WELL</u>	API Number: <u>045-21522</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429288</u>	Type: <u>WELL</u>	API Number: <u>045-21523</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429289</u>	Type: <u>WELL</u>	API Number: <u>045-21524</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429290</u>	Type: <u>WELL</u>	API Number: <u>045-21525</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429292</u>	Type: <u>WELL</u>	API Number: <u>045-21527</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429294</u>	Type: <u>WELL</u>	API Number: <u>045-21529</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429296</u>	Type: <u>WELL</u>	API Number: <u>045-21531</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429297</u>	Type: <u>WELL</u>	API Number: <u>045-21532</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429298</u>	Type: <u>WELL</u>	API Number: <u>045-21533</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429299</u>	Type: <u>WELL</u>	API Number: <u>045-21534</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

Inspector Name: Colby, Lou

Facility ID:	429300	Type:	WELL	API Number:	045-21535	Status:	XX	Insp. Status:	RI
Facility ID:	429301	Type:	WELL	API Number:	045-21536	Status:	XX	Insp. Status:	RI
Facility ID:	429302	Type:	WELL	API Number:	045-21537	Status:	XX	Insp. Status:	RI
Facility ID:	429306	Type:	WELL	API Number:	045-21541	Status:	XX	Insp. Status:	RI
Facility ID:	429307	Type:	WELL	API Number:	045-21542	Status:	XX	Insp. Status:	RI
Facility ID:	429308	Type:	WELL	API Number:	045-21543	Status:	XX	Insp. Status:	RI
Facility ID:	429309	Type:	WELL	API Number:	045-21544	Status:	XX	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? FailComment What appears to be unused equipment is in main Well Pad area; refer to photos attached.Corrective Action Remove any unneeded / unused equipment from site.Date **05/04/2018**Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Weather prevented detailed Vegetation assessment.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date 05/04/2018Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment: [Weather prevented detailed Stormwater assessment.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	414437	1630785	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102835	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428159