

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2018

Submitted Date:

04/07/2018

Document Number:

680303139**FIELD INSPECTION FORM**Loc ID 454194 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10657Name of Operator: PCR OPERATING LLCAddress: 4040 BROADWAY STREET #510City: SAN ANTONIO State: TX Zip: 78209**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Wehrer, Gene	(970) 380-4860	gwehrer@passcreekresource.com	<a href="#">Adena Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454196	WELL	XX	03/05/2018		087-08224	JESS 158-13-43	DG

**General Comment:**[Spud](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off county road		
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	Spud - Sign at entrance to site off county road.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Satisfactory

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 0		
Comment:	Drilling and related equipment on-site. No production equipment for inventory.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 454196 Type: WELL API Number: 087-08224 Status: XX Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Nebco #12 Pusher/Rig Manager: Gary Naill  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 800 Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: YES Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: Solid on-site

**Comment:** Spud. Begin drilling and reparing to set surface casing.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>Spud</u>	<u>schureky</u>	<u>04/07/2018</u>