

Inspection Photos

Loc# 431328

Operator: Caerus

Inspection Number: 680102845

Inspection Date: 3/30/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to North.

March 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 431328



Photo#2:
Overview of Location to Southwest.

March 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 431328



Photo#3:
Pit located off Northwest edge of Location .

March 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 431328



Photo#4:

Close ups of material in Pit located off Northwest edge of Location.

Photo#5:

March 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 431328



Photo#6:
Roll off at North end of site is fenced with Panels and netted.

March 30 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 431328