

# *Inspection Photos*

*Loc# 335907*


*Operator: Caerus*

*Inspection Number: 680102847*

*Inspection Date: 3/29/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to South.

March 29 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335907



Photo#2:

Perimeter controls are well stabilized and vegetation is established on Fill slopes.

March 29 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335907



Photo#3:

Current Drilling Operations are causing some disturbance to areas of pad edge berms & fill slopes..

March 29 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335907