

**Inspection Photo**  
**GMR 34-2B**  
**API# 045-10001**  
**Inspection # 689300826**



**Location Photo**



**Location photo**

**Inspection Photo**  
**GMU 34-2B**  
**API# 045-10001**  
**Inspection # 689300826**



**Missing signs on chemical container**



**Missing signs on chemical container**



**Inspection Photo**  
**GMU 34-2B**  
**API# 045-10001**  
**Inspection # 689300826**



**Location photo**



**Missing lease entrance sign**