

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2018

Submitted Date:

04/10/2018

Document Number:

680303152

FIELD INSPECTION FORM

Loc ID 312202 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 88370
Name of Operator: TIMKA RESOURCES LTD
Address: 2116 EAST HIGHWAY 402
City: LOVELAND State: CO Zip: 80537

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Pivonka, Todd		pivonka2010@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219441	WELL	IJ	02/01/2017	ERIW	075-06348	NORTH MINTO J SAND UNIT 1	IJ

General Comment:

P&A Day (1)

Location

Lease Road:			
Type	Access		
comment:	Two track		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	Upon completion of P&A, remove all equipment, cut-purge-cap all flowlines, begin reclamation process.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 219441 Type: WELL API Number: 075-06348 Status: IJ Insp. Status: IJ

Cement

Cement Contractor

Contractor Name: Timka Resources,

Contractor Phone: 970-667-9861

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: MIRU, unseat pump, pull/laydown rods. Set auxillary equipment. Shut in - shut down for night.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Continue BMP for stormwater erosion management until final reclamation is approved.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
P&A Day (1). MIRU, unseated pump, setting down rods and setting auxillary equipment. Windy conditions.	schureky	04/10/2018