

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401587133
Date Received:
03/26/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10608

Name of Operator: BNN WESTERN LLC

Address: 370 VAN GORDON STREET

City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Gopsill, Eric

eric.gopsill@bnn-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684905079

Inspection Date: 02/27/2018

FIR Submit Date: 02/27/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BNN WESTERN LLC

Company Number: 10608

Address: 370 VAN GORDON STREET

City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: 438078

Location Name: Horsetail Number: 19N-1924M-R County: WELD

Qtrqtr: SWSE Sec: 19 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.818864 Longitude: -103.794093

FACILITY - API Number: 05-123-00 Facility ID: 440007

Facility Name: Horsetail Number: 19N-1924M-R

Qtrqtr: SWSE Sec: 19 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.818864 Longitude: -103.794093

CORRECTIVE ACTIONS:

1 ☒ CA# 114567

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 03/27/2018

Response: CA COMPLETED

Date of Completion: 03/26/2018

The stained soil at the aboveground line was been removed. See attached Soil Sampling Report.

Operator
Comment:

COGCC Decision: Approved via an AMI

COGCC
Representative:

2 ☒ CA# 114568

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 03/27/2018

Response: CA COMPLETED

Date of Completion: 03/26/2018

Operator
Comment:

The stained soil at the loadout has been removed. See attached soil sampling report.

COGCC Decision: Approved via an AMI

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Eric Gopsill

Signed: _____

Title: Director: water solutions

Date: 3/26/2018 2:35:06 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|--------------------------|
| 401587133 | FIR RESOLUTION SUBMITTED |
| 401587161 | soil sampling report |

Total Attach: 2 Files