



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Clay Elkins (celkins@gobrainstorm.net)  
Submission Date: Mar 20, 2018 8:18:20 AM MDT  
Server Receive Date: Mar 20, 2018 3:37:53 PM MDT  
Reference Number: 20180320-1874987165  
Location: 3601 N 1st St, Bloomfield, NM 87413, United States  
Mar 20, 2018 8:18:12 AM MDT [ [View Map](#) ]

## Information

Name celkins@gobrainstorm.net  
Date Mar 15, 2018  
Well Name JONES, LAURANCE GAS UNIT A 1  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Compliance Inspection Actions  
Fencing  
Clean up Operator Debris  
Clean Up Land Owner Debris  
Clean Up Contaminated Soils  
Replaced/Repaired Tank Signs  
Grading of Well Pad

## Picture North to South



## Picture South to North



Picture East to West



Picture West to East



Additional photos

