



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Mar 21, 2018 12:12:21 PM MDT
Server Receive Date:	Mar 21, 2018 12:12:26 PM MDT
Reference Number:	20180321-1875061634
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Mar 21, 2018 12:11:50 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Mar 19, 2018
Well Name	LE PLATT GAS UNIT A 1
API Number	50670720200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

cleaned up weed debris and trash on site.

