

Inspection Photos

04/10/2018

Operator: LEGADO DJ, LLC - 200039

Location ID: 388436

Inspection Doc. Number: 682503223

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: LEGADO DJ, LLC - 200039
Location ID: 388436



Photo 1: Photo taken from the east end of the location, facing southwest. Photo shows areas appear to have had additional reclamation activities conducted. Area appears to have been reseeded and stabilized with a mulch.



Photo 2: Photo taken from the east end of the location, facing northwest. Photo shows areas appear to have had additional reclamation activities conducted. Area appears to have been reseeded and stabilized with a mulch.

Inspection Photos
Operator: LEGADO DJ, LLC - 200039
Location ID: 388436



Photo 3: Photo taken from the west end of the location, facing east. Photo shows areas appear to have had additional reclamation activities conducted. Area appears to have been reseeded and stabilized with a mulch.



Photo 4: Photo taken from the east end of the location, facing south. Photo shows areas appear to have had additional reclamation activities conducted. Area appears to have been reseeded and stabilized with a mulch.