

Inspection Photos

04/10/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312292

Inspection Doc. Number: 682503225

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 1: Photo taken from the central area of the location, facing north. Photo shows erosion degradation appears to have been repaired. However stabilization controls do not appear to have been implemented and revegetation activities do not appear to have been conducted.



Photo 2: Photo taken from the central area of the location, facing east. Photo shows erosion degradation appears to have been repaired. However stabilization controls do not appear to have been implemented and revegetation activities do not appear to have been conducted.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 3: Photo taken from the central area of the location, facing east. Photo shows erosion degradation appears to have been repaired. However stabilization controls do not appear to have been implemented and revegetation activities do not appear to have been conducted.



Photo 4: Photo taken from the south end of the location, facing southeast. See comments under photo 3

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 5: Photo taken from the south end of the location, facing south. See comments under photo 3



Photo 6: Photo taken from the south end of the location, facing southeast. See comments under photo 3

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 7: Photo taken from the south end of the location, facing northwest. Photo shows tinhorn has been removed.



Photo 8: Photo taken from the south end of the location, facing north. See comments under photo 3

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 9: Photo taken from the southeast end of the pit, facing west. See comments under photo 3



Photo 10: Photo taken from the southwest end of the pit, facing south. See comments under photo 3

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 11: Photo taken from the southwest end of the pit, facing southeast. See comments under photo 3



Photo 12: Photo taken from the southwest end of the pit, facing east. See comments under photo 3

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312292



Photo 13: Photo taken from the southwest end of the pit, facing west. See comments under photo 3



Photo 14: Photo taken from the southwest end of the pit, facing north. See comments under photo 3



Photo 15: Photo taken from the east end of the pit. Photo shows gulley erosion has been repaired.