

Inspection Photos

04/10/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312291

Inspection Doc. Number: 682503227

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 1: Photo taken from the east end of the location, facing southeast. Photo shows erosion degradation appears to have been repaired. However stabilization controls do not appear to have been implemented and revegetation activities do not appear to have been conducted.



Photo 2: Photo taken from the east end of the location, facing southeast. See comments under photo 1

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 3: Photo taken from the east end of the pit, facing southeast. See comments under photo 1



Photo 4: Photo taken from the southeast end of the pit, facing west. See comments under photo 1

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 5: Photo taken from the south end of the pit, facing west.
See comments under photo 1



Photo 6: Photo taken from the southwest end of the pit, facing west.
See comments under photo 1

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 7: Photo taken from the west end of the location, facing west. See comments under photo 1



Photo 8: Photo taken from the west end of the location, facing north. See comments under photo 1