

Inspection Photos
Location Name: TEP Pit 414554
4/11/2018



Discharge from Tank Battery looking southeast-pipe is on liner



Tank Battery looking West



Pit looking Northeast



Electronic leak detection on south bank