

# Final Reclamation Inspection

April 11, 2018

Operator: Blue Chip Oil Inc- 8840

API: 05-123-14512

Inspection Document #: 682403471

Weld County, CO

NESE Section 25 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SLOAN #3  
API: 05-123-14512



**Photo 1.** Photo taken from the battery location, facing South. Operator has removed the equipment from location. However, weed debris remains at location along the perimeter fences.

Inspection Photos  
Location Name: SLOAN #3  
API: 05-123-14512



**Photo 2.** Photo taken from the western battery location, facing South. Photo illustrates weed debris along the perimeter fence.

Inspection Photos  
Location Name: SLOAN #3  
API: 05-123-14512



**Photo 3.** Photo taken from the northern battery location, facing West. Photo illustrates weed debris along the perimeter fence.