

Final Reclamation Inspection

April 11, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-18601

Inspection Document #: 682403474

Weld County, CO

NWSW Section 29 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TOLLGATE FARMS #29-12G6
Well API: 05-123-18601



Photo 1. Photo taken from the battery location, facing South. No further work has been performed since the previous inspection. Operator previously indicated a variance would be submitted.



Photo 2. Photo taken from the battery location, facing East. See comments under Photo 1.