

BOSELY SG 43-22
Api: 05-045-07243
Inspection # 689701279



Location photo.

BOSELY SG 43-22
Api: 05-045-07243
Inspection # 689701279



Write in tank volume on tank label not legible.

BOSELY SG 43-22
Api: 05-045-07243
Inspection # 689701279



Just before location washing of road cutting into v ditch. 39.42140 108.08775.

BOSELY SG 43-22
Api: 05-045-07243
Inspection # 689701279



Sediment build up in culvert. 39.42103 108.08820

BOSELY SG 43-22
Api: 05-045-07243
Inspection # 689701279



Sediment build up in culvert. 39.42103 108.08820