

Interim Reclamation and Stormwater Inspection

April 11, 2018

Operator: SRC ENERGY INC- #10311

Location ID: 448368

Inspection Document #: 682403481

Weld County, CO

NESE Section 36 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Orr State
Location ID: 448368



Photo 1. Photo taken from the western location, facing North. Photo illustrates the Operator has started interim reclamation activities but has failed to complete interim reclamation by the due date of 12/2/2017.

Inspection Photos
Location Name: Orr State
Location ID: 448368



Photo 2. Photo taken from the western location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Orr State
Location ID: 448368



Photo 3. Photo taken from the western location, facing East. See comments under Photo 1. Operator claims that a pipeline being installed along the eastern location and supplies/equipment being stored on location is the reason for holding up reclamation.

Inspection Photos
Location Name: Orr State
Location ID: 448368



Photo 4. Photo taken from the western location, facing West. Photo illustrates reference areas beyond the Orr State location.

Inspection Photos
Location Name: Orr State
Location ID: 448368



Photo 5. Photo taken from the northwest well pad location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Orr State
Location ID: 448368



Photo 6. Photo taken of the topsoil stockpile along the western location. Operator has failed to prevent weed establishment per Rule 1002.c.