

**Inspection Photo**  
**GMR 34-14A**  
**API# 045-10957**  
**Inspection # 689300817**



**Location photo #1**



**# 2 oil stained ground**

**Inspection Photo  
GMR 34-14A  
API# 045-10957  
Inspection # 689300817**



**photo #3 oil stained ground**



**Photo #4 Stained soil around filter pot**

**Inspection Photo  
GMR 34-14A  
API# 045-10957  
Inspection # 689300817**



**photo #5, staining with in the tank  
containment**



**Photo #6, Stored/unused equipment near  
tanks**

**Inspection Photo**  
**GMR 34-14A**  
**API# 045-10957**  
**Inspection # 689300817**



**Photo # 7 stored equipment North fence**

